

STRUCTURAL ENGINEERING LABORATORY/ COMPOSITES TECHNOLOGY CENTRE

26.02.2007

Dr. P. Alagusundaramoorthy Associate Professor

To M/S Pishon Concrete Test No. 946, 51 Block VOC Nagar Tondiarpet Chennai – 600 081

Sir,

Sub: Assessment of Health of Sea Water Intake Pump House and Jetty Structure at SMPP-NTPC Ltd. – Reg.

Ref: IC/06-07/OEC/NTPC/RSUN

With reference to the above subject, you are requested to conduct UPV, Half Cell Potential measurements on the concrete portion of Sea Water Intake Well, UPV measurements on two piles on approach Jetty and measure the depth of sea bed near Sea Water Intake Well and approach Jetty at NTPC, Vizagapatnam, Andhra Pradesh, and to submit the report to access the condition of the structures.

Thanking you,

Yours faithfully

| mgusunum umoortiny)

26.02.200)